

From: Piro, Peter (DPH)
Sent: Friday, February 19, 2010 9:24 AM
To: Nassif, Julianne (DPH)
Cc: Salemi, Charles (DPH)
Subject: Painting

Dear ppiro,

Your request has been logged as Maintenance Request #**M105664**.
Please, write this number down or print this page for your records and future reference.

Thank you,

The Maintenance Team

PIC#	5301
Program	Drug Lab/SLI

**Maintenance Request
#M105664**

		Status	New Request
Location	Tower		
Room #	361	Requested By	ppiro
Phone	6179836634	Authorized By	
Needed By Date	2/28/2010		
Request Type	Maintenance		

Project Description:

Julie Nassif plans on having the Drug Lab walls painted and possibly the cabinets as well. Please explain to Julie the root cause of the drywall damage to the exterior walls and the solution. In addition, are there any types of drywall that could mitigate damage in problematic applications?